

UNITED STATES PATENT AND TRADEMARK OFFICE
CERTIFICATE OF CORRECTION

PATENT NO. : 6,950,459 B1
DATED : September 27, 2005
INVENTOR(S) : S. Palm

Page 1 of 1

It is certified that error appears in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

Title page.

Item [56], **References Cited, OTHER PUBLICATIONS**, should include:

-- ITU-T recommendation G.994 ("Handshake Procedures for Digital Subscriber Line (DSL) Transceivers"), published by the International Telecommunication Union in February, 2001; --.

Column 20.

Line 23, after "comprising" insert -- : --.

Line 34, "system, the" should be -- of the first predetermined --.

Line 38, "indication" should be -- indicating --.


Line 52, after "wherein" insert -- the --.

Column 21.

Line 5, "transmits" should be -- transmit --.

Signed and Sealed this

Ninth Day of May, 2006



JON W. DUDAS
Director of the United States Patent and Trademark Office